

Guideline	ca. 630 m	Implementation		
	Standard machine hoe + hand hoe	21,6m	48 rows	1,4 ha
	Control	5,4m	12 rows	0,3 ha
ca. 4,0 ha	Farming Revolution with hand hoe	48,6m	108 rows	3,1 ha
				Sum 4,4 ha
ca. 0,5 ha	Farming Revolution without hand hoe	10,8m	24 rows	0,68 ha
ca. 0,5 ha	Farming Revolution + 1 hoeing pass shortly before row closure	10,8m	24 rows	0,68 ha
		Sum:	97,2m	216 rows
				6,1 ha